

PARTS CATALOG

FOR

LETOURNEAU

MODEL

G6

CARRYALL SCRAPER

EFFECTIVE WITH SERIAL NUMBER

S3583G6 & UP

S3700G6A & UP

LeTOURNEAU-WESTINGHOUSE COMPANY

Formerly



R.G. LETOURNEAU INC

Peoria, Ill. - Stockton, Calif.

Cable Address "Bobletorno"

ALWAYS GIVE MACHINE NUMBER WHEN ORDERING PARTS

E-1218 HOIST LINE CABLE $\frac{1}{2} \times 6 \times 19-65$ FEET LONG


From Right Drum of Power Unit Enter Cable in Bottom of Swivel Sheave.....**A**
 Then Up and Over Sheave.....**D**
 Then Up and Alongside Spring Pipe to the Top of Sheave.....**F**
 Down to Back of Sheave.....**J**
 Then Through Hole in Body and Enter Right Sheave in Housing.....**N**
 Then Up to Right Side Sheave in Housing.....**L**
 Then Reeve Cable Back and Forth in Housings L & N and Dead End Cable in Cable Wedge.....**M**

E-1218 DUMP LINE CABLE $\frac{1}{2} \times 6 \times 19-65$ FEET LONG

From Left Drum in Power Unit Enter Cable in Top of Swivel Sheave.....**B**
 Then Down and Around Sheave.....**C**
 Then Up the Side of Spring Pipe and Enter Cable in the Outside Sheave in Housing.....**H**
 Then Down to the Bottom of Left Sheave in Apron Housing.....**E**
 Then Back Up to Inside of Housing.....**H**
 Then Back Down to Right Sheave in Housing.....**E**
 Then Up and Dead End on the Side of Housing.....**H**

E-5287 TAIL GATE RETURN CABLE $\frac{1}{2} \times 6 \times 19-8\frac{1}{2}$ FEET LONG


After Spring Cable is in Place and With Tail Gate All the Way Up Anchor Cable at Cable Wedge.....**K**
 Then Run Cable Around Spiral Sheave Groove and Dead End on Spiral Sheave Wedge.....**I**



NOTE: Right and Left Determined by Standing Behind Equipment and Looking Forward.

CABLE THREADING DIAGRAM


ALWAYS GIVE MACHINE NUMBER WHEN ORDERING PARTS



PRINTED IN U.S.A.

BODY


ALWAYS GIVE MACHINE NUMBER WHEN ORDERING PARTS



116

TAIL GATE & APRON

ALWAYS GIVE MACHINE NUMBER WHEN ORDERING PARTS



PRINTED IN U.S.A.

120

THROW ARM

ALWAYS GIVE MACHINE NUMBER WHEN ORDERING PARTS

FRONT AXLE ASSEMBLY

PRINTED IN U.S.A.

- 2 BUSHING----- C- 518
- 1 NUT----- C-59
- 1 COTTER KEY---- C-1561

- 2 BOLT----- C-1685
- 2 NUT----- C-1524
- 2 WASHER----- C-1540

- 1 FRONT AXLE
STRUCTURE----- E-3075

- 1 CAP ----- C-5425
- 2 CAPSCREW ----- C-1600
- 2 BUTTONHEAD----- C-1330

- 1 FORGING ----- C-4993
- 1 PIN ----- C-521
- 1 BLOCK ----- C-1409
(PARTS OF ASSEM-- C-6142)


- 2 BUSHING----- C-518

- C-511 FORGING----- 1

- C-1591 BOLT----- 4
- C-1533 NUT ----- 4

- C- 59 NUT----- 1
- C-1561 COTTER KEY---- 1


- C-1685 BOLT ----- 2
- C-1524 NUT ----- 2
- C-1540 WASHER----- 2




INSERT IN MISCELLANEOUS SECTION OF MASTER PARTS CATALOG

[illegible]


SPIRAL SHEAVE





7.50 X 20 BUDD WHEEL ASSEMBLY E-2871

ALWAYS GIVE MACHINE NUMBER WHEN ORDERING PARTS



7.50 X 20 WHEEL & AXLE

EFFECTIVE WITH SERIAL NO. S3700G6A

ALWAYS GIVE MACHINE NUMBER WHEN ORDERING PARTS